



N.T. & H. ENTERPRISES, INC.
SILVER RECOVERY SERVICE
SILVER FLAKE — USED OR NEW FILM



P.O. BOX 306 • HALSTEAD, KANSAS 67056 • 609 MCNAIR
TELEPHONE 1-316-835-2088 FAX 1-316-835-2730

SALES AND SERVICE REPRESENTATIVES:
NEVIN HENDERSON
FRANK WHITESELL
GERALD ADAMS

ATTENTION!!!

BEFORE CLEANING PROCESSOR, YOU MUST FIRST---
DRAIN SILVER LADEN FIXER INTO THE SILVER RECOVERY UNIT. THEN
CLAMP OFF, DISCONNECT, OR BYPASS SILVER RECOVERY UNITS.
NO DEBRIS, CLEANING SOLUTIONS, OR RINSE WATER SHOULD BE PERMITTED TO ENTER SILVER RECOVERY UNIT.

AFTER CLEANING PROCESSOR, YOU MUST --
UNCLAMP, RECONNECT OR UN-BYPASS SILVER RECOVERY UNITS.

IF THE PROCESSOR HAS BYPASS VALVES (EITHER OEM OR AFTERMARKET), PLEASE MAKE SURE THAT THEY ARE IN THE NORMAL POSITION WHEN THROUGH CLEANING THE PROCESSOR

FOLLOWING THESE INSTRUCTIONS WILL ENABLE THE SILVER RECOVERY EQUIPMENT TO FUNCTION AT PEAK EFFICIENCY AND TO RETURN THE MAXIMUM RECOVERED SILVER YIELD INCOME AVAILABLE TO THIS FACILITY.

FAILURE TO COMPLY WITH THE ABOVE INSTRUCTIONS CAN RESULT IN CLEANING MATERIALS CLOGGING THE SILVER RECOVERY UNIT, AND WILL SEVERELY RESTRICT THE EFFICIENCY OF THE SILVER RECOVERY UNIT.

THIS MAY CAUSE NON-COMPLIANCE WITH FEDERAL, STATE, AND LOCAL E.P.A. REGULATIONS.

NON-COMPLIANCE WITH THESE REGULATIONS CAN RESULT IN FINES OF UP TO \$6000.00 PER DAY AND CAN BE LEVIED AT BOTH THE FACILITY AND THE PROCESSOR SERVICE COMPANY.

CHECK SILVER RECOVERY UNITS WEEKLY TO ENSURE THEY'RE OPERATING.

PLEASE POST THIS NOTICE IN A CONSPICUOUS LOCATION NEAR PROCESSOR TO ENSURE COMPLIANCE.